

February 15, 1978

ENGINEERING MEMO#394

TO: MEMO DISTRIBUTION  
FROM: C. BLAND  
SUBJECT: SIDE MARKER LAMPS

As a product improvement, the present side marker lampswiring will be revised to flash with front and rear turn signals.

This change will be made with a minimum of obsolescence.

Following is a complete list of the parts affected.

ITEM	NAME	B or M	OLD PART NUMBER	NEW PART NUMBER	INT NEW FOR OLD	AVAIL AFTER CHG	REMARKS
1	Forward Lamp Harness Asm	B	705732	Chg B	YES	YES	Rework
2	Rear Lamp Harness Asm	B	651715	Chg C	YES	YES	Rework
3	Socket Asm-Marker Lamp-RR	B	647051	653341	NO	YES	Rework
4	Socket Asm-Marker Lamp-Frt	B	647052	653342	NO	YES	Rework