

October 22, 1962

Rev. 11-19-62

Rev. 11-28-62

ENGINEERING MEMORANDUM #22

TO: J. Stout, P. Visser, R. G. Fuller, J. Coleman, S. Hori, E. Horrigan,  
K. Luke, F. Leamy, R. McCulfor, R. Smith, F. Baldwin, C. Cornwell,  
E. Nelson, J. Copeland, T. Bedard, J. Temple 4, K. Bothe,  
L. Hilsky 4, A. Radke 3, D. Markin, B. Herrington(8), W. Asselin,  
D. Bach, A. Goedhart, S. Megyesi.

FROM: S. Wilson

SUBJECT: WEATHERSEAL REVISIONS

List of New Parts Required

639451 Weatherseal Assem. - Frt. Door Opening LH  
639452 Weatherseal Assem. - Frt. Door Opening RH  
639453 Weatherseal Assem. - Rear Door Opening LH A-11 A-12  
639454 Weatherseal Assem. - Rear Door Opening RH A-11 A-12  
639773 Weatherseal Assem. - Rear Door Opening LH A-12W, A-12W6 & 8  
639774 Weatherseal Assem. - Rear Door Opening RH A-12W, A-12W6 & 8  
639775 Weatherseal Assem. - Center Door Opening LH A-12W6 & 8  
639776 Weatherseal Assem. - Center Door Opening RH A-12W6 & 8  
640401 Weatherseal - Frt. Door Opening - Frt. LH  
640402 Weatherseal - Frt. Door Opening - Frt. RH  
640399 Insert - Center Pillar Rear W/Seal  
640400 Section - Door Opening W/Seal (Ref. Drwg. Only)

List of Parts to be Cancelled

633443 Weatherseal Assem. - Frt. Door Upper LH  
633444 Weatherseal Assem. - Frt. Door Upper RH  
633445 Weatherseal Assem. - Rear Door Upper LH A-11 A-12  
633446 Weatherseal Assem. - Rear Door Upper RH A-11 A-12  
635163 Weatherseal Assem. - Rear Door Upper LH A-12W, A-12W6 & 8  
635164 Weatherseal Assem. - Rear Door Upper RH A-12W, A-12W6 & 8  
635495 Weatherseal Assem. - Center Door Upper LH A-12W6 & 8  
635496 Weatherseal Assem. - Center Door Upper RH A-12W6 & 8  
634857 Weatherseal - Pillar Lower LH  
634858 Weatherseal - Pillar Lower RH  
634866 Insert - Center Pillar Rear W/Seal  
634864 Insert - Pillar Frt. Upper W/Seal  
163158 Screw - #8 x 3/8 (Usage Change Only)

~~A-12 change is to be effective as soon as new is available.~~

~~A-11 change is to be effective when stock is depleted.~~

~~11-19-62 A-12W, A-12W6 & 8 is to be effective when stock is depleted.~~

~~11-19-62 A-12W, A-12W6 & 8 is to be effective as soon as new is available.~~

Old weatherseals may be serviced with new.

11-28-62 This revision is to be effective on all models as soon as possible regardless of stock on hand. Chassis #7334 A-11, A-12  
7343 A-12W  
636 A-12W6&8

Chassis no's. added 6-13-63: