

January 30, 1963

ENGINEERING MEMORANDUM #35

TO: J. Stout, R. Fuller, J. Coleman, S. Hori, E. Horrigan,
K. Luke, F. Leamy (3), R. McCulfor, R. Smith, C.
Cornwell, E. Nelson, J. Copeland, T. Bedard, J. Temple (4),
K. Bothe, L. Hilsky (4), A. Radke (3), D. Markin,
B. Herrington (8), W. Asselin, D. Bach, F. Baldwin, S. Wilson
A. Goedhart, S. Megyesi.

FROM: P. Visser

SUBJECT: FLOOR SHIFT TYPE TRANSMISSIONS, PART NUMBERS
95376 AND 95377

Whenever these floor shift type transmissions, which were recently provided with rear thimbles against oil leakage, have to be equipped with back up light switch assemblies, the rear thimble of the right hand rail should be removed and replaced by a plug, part number 626588.

This plug acts as an oil seal and is flexible enough to allow the right hand rail in reverse position to actuate the back up light switch.

Tooling is requested to make up a round bar with rounded corners at one end so that the plug can be tapped easily in place into the yoke bar housing as shown on SK-2364 and SK-2365.