

March 30, 1964

ENGINEERING MEMORANDUM #57

TO: J. Stout, P. Visser, R. Fuller, J. Coleman, S. Hori, E. Horrigan,  
K. Luke, F. Leamy (3), R. McCulfor, R. Smith, C. Cornwell, E. Nelson,  
J. Copeland, T. Bedard, J. Temple (4), K. Bothe, L. Hilsky (4),  
A. Radke (3), D. Markin, B. Herrington (8), W. Asselin, D. Bach,  
F. Baldwin, A. Goedhart, S. Megyesi.

FROM: S. Wilson

SUBJECT: CHANGES REQUIRED TO INCREASE PROPELLOR SHAFT CLEARANCE  
FOR MODEL A-11, A-12, A-12W, & A-12E.

PARTS TO BE REVISED FOR MODEL A-11, A-12, A-12W

<u>PART NO.</u>	<u>NAME</u>	<u>CHANGE</u>
640522	Pan - Front Floor	Change V
640553	Pan - Rear Floor	Change E

PARTS TO BE REVISED FOR MODEL A-12E

<u>PART NO.</u>	<u>NAME</u>	<u>CHANGE</u>
642313	Pan - Front Floor Center	Change A
642319	Pan - Front Floor Rear (New - Make From 640522)	
642311	Member - Center Floor Cross Rear (Replaces 640554)	New
642312	Member - Center Floor Cross Center	Change E
640522	Pan - Front Floor	Change V
642331	Pan - Front Floor (Frt.)	New
640553	Pan - Rear Floor	Change E
641500	Member Assem. - (Tr. Fl. Cr. Rear Repl. by 641167)	
641173	Pan Assem. - Rear Floor	New

This revision is to be incorporated as soon as all dies have been reworked. All parts affected must be incorporated simultaneously.