

December 15, 1964

ENGINEERING MEMO #84

TO: J. Stout, G. Orwig, R. Fuller, S. Hori, E. Horrigan, F. Leamy (3)
 R. McCulfor, A. Radke (3), W. Asselin, R. Smith, A. Goedhart,
 B. Lewis, V. May, E. Nelson, C. Cornwell, S. Megyesi, B. Herrington(8)
 R. Bach, D. Markin, F. Baldwin, J. Copeland, J. Coleman, T. Bedard,
 K. Bothe, L. Hilsky (4), J. Temple (4), W. VanHorn.

FROM: S. Wilson

SUBJECT: INSTRUMENT PANEL CLOCK

We have been advised by the purchasing department that our current clock no. 643061 will no longer be available when our current stock is depleted. Therefore we will revert back to a clock which is similar to that used on our early A-12 models. Reference previous memo #62 for early design.

<u>NEW NO.</u>	<u>OLD NO.</u>	<u>DESCRIPTION</u>
643161	643064	Clock Assem.-Instr. Panel (Compl.)
643162	643061	Clock Assem.-Instr. Panel
642610	642569	Bracket-Instr. Panel Clock
642609	642567	Panel-Instr. Center (A-12, A-12W, A-12E)
640871	640824	Panel-Instr. Center (A-12W6 & 8)
-----	642568	Bezel-Instr. Panel Clock
639256	643066	Socket & Harness Assem.-Clock (Reinstate 639256)
	643065	Socket & Harness Assem.-Clock(Furn. Part)
-----	120614	Nut - #10-32 Hex. (Remove 2 for Clock)
120217		Lockwasher- #10 Med. Spr. (Add 1 for Clock)
	138479	Lockwasher -#10 Ext. Tooth (Remove 2 for Clock)

This revision incorporated on Chassis No. 26421 for Models A-12, A-12W, A-12E. Incorporated on Chassis No. 1371 for A-12W6M & A-12W8M.

Chassis Numbers Added 4-8-65