

DATE: March 17, 1964

TO: J. Stout, R. G. Fuller, J. Coleman, S. Hori, E. Horrigan, K. Luke  
F. Leamy (3), R. McCulfor, R. Smith, C. Cornwell, E. Nelson,  
J. Copeland, T. Bedard, J. Temple (4), K. Bothe, L. Hilsky (4),  
A. Radke, D. Markin, B. Herrington (8), W. Asselin, R. Bach,  
F. Baldwin, A. Goedhart, S. Wilson, S. Megyesi.

FROM: P. Visser

SUBJECT: Cable Assembly Battery to Sol. Switch

With the introduction of 701261 replacing 97570, it is necessary to place the front mounted battery in such a position that the negative pole is to the front of the car and subsequently the positive pole, to which afore mentioned cable is fastened, to the rear of car.

Per Mr. Leamy, writer was informed that of 97570, 907 jobs are on hand and:

600 Due March  
500 Due 4-14-64  
500 Due 4-29-64  
500 Due 5-14-64  
500 Due 5-29-64

Writer request Purchasing Dept. and Production Control to collaborate on the acquisition of the 702161 item, therewith reducing the carry-over period of the old cable.